

Post date:

Sunday, December 1, 2013 - 18:46

Last modified:

Sunday, December 14, 2014 - 14:20

Ive never been a fan of the lever lock screws for locking the table on a Mill so i made some round knurled ones. I dont have alot of material here at home so i bought four bolts, knurled a chuck of 2" 1080, drilled, bored a recess for the bolt heads to sit in, welded then faced to clean them up.



- Started with a 2" piece of 1018 around 6" long.
- Took a skim pass over the OD and knurled the OD over a 3" span.
- Drilled, counter bored and cut off each one at a 1/2".

Note: i am no welder :-)

Image Gallery:

- [View the full image](#)



- [View the full image](#)



• [View the full image](#)




• [View the full image](#)



• [View the full image](#)



• [View the full image](#)



Mobile QR Barcodes:

[Save Article as PDF](#)



Current URL Address



Other site pages which link here:

Category:

[Industrial Hobbies Mill Modifications](#)
